

STRUCTURETECH ENGINEERING PC
Forensic Investigation Report

365 BROADWAY
NEW YORK, NY 10013



Photograph 11: Game Room and east vault: cracking noted in the Game Room concrete slab below the tile floor finish.



Photograph 12: Game Room: mortar joint cracks and through-tile cracks noted throughout the Game Room.

STRUCTURETECH ENGINEERING PC
Forensic Investigation Report

365 BROADWAY
NEW YORK, NY 10013



Photograph 13 mortar joint cracks and through-tile cracks noted near north wall



Photograph 14: Cellar level: crack noted in the wall and stone base at the north wall

STRUCTURETECH ENGINEERING PC
Forensic Investigation Report

365 BROADWAY
NEW YORK, NY 10013



Photograph 15: Cellar level: crack noted in stone wall and floor at the north wall




Photograph 16: Cellar level: crack noted in stone wall and floor at the north wall

STRUCTURETECH ENGINEERING PC
Forensic Investigation Report

365 BROADWAY
NEW YORK, NY 10013



Photograph 17: Cellar level: crack noted in stone wall and floor at the north wall



Photograph 18: Cellar level: crack noted in stone wall and floor at the north wall

STRUCTURETECH ENGINEERING PC
Forensic Investigation Report

365 BROADWAY
NEW YORK, NY 10013




Photograph 19: First Floor: crack noted in the marble stone wall and floor at mail room



Photograph 20: First Floor: crack noted in the marble stone wall and floor at mail room

STRUCTURETECH ENGINEERING PC
Forensic Investigation Report

365 BROADWAY
NEW YORK, NY 10013




Photograph 21: First Floor: crack noted in the marble stone floor at mail room



Photograph 22: First Floor: crack noted in the marble stone wall and floor at mail room

STRUCTURETECH ENGINEERING PC
Forensic Investigation Report

365 BROADWAY
NEW YORK, NY 10013



Photograph 23: First Floor: diagonal crack noted in the wall at the door of unit 2A



Photograph 24: First Floor: diagonal crack noted in the wall at the door of unit 2A




Photograph 25: First Floor: sheet rock crack noted in the ceiling of unit 2A



Photograph 26: First Floor: sheet rock crack noted in the ceiling of unit 2A



Photograph 27: First Floor: sheet rock crack noted in the ceiling of unit 2A



Photograph 28: First Floor: sheet rock crack noted in the ceiling of unit 2A

STRUCTURETECH ENGINEERING PC
Forensic Investigation Report

365 BROADWAY
NEW YORK, NY 10013



Photograph 29: North wall: the new building 371 Broadway has been built adjacent to 365 Broadway with no gap in between.




Photograph 30: North wall: general view of north wall looking south.

STRUCTURETECH ENGINEERING PC
Forensic Investigation Report

365 BROADWAY
NEW YORK, NY 10013



Photograph 31: North wall: general view of north wall looking east.



Photograph 32: North wall: general view of north wall looking south & up.

STRUCTURETECH ENGINEERING PC
Forensic Investigation Report

365 BROADWAY
NEW YORK, NY 10013



Photograph 33: General view of east elevation from Broadway looking west.